03560.002699



PATENT



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
TOSHIO KAMESHIMA ET AL.	:	Examiner: Nelson D. Hernandez Group Art Unit: 2612
Appln. No.: 09/748,219)	Group Art Onit. 2012
Filed: December 27, 2000	;) ;	Certificate
For: AREA SENSOR, INPUT APPARATUS)	FEB 0 2 2006
HAVING THE SAME, AND METHOD OF DRIVING THE AREA SENSOR	:)	of Correction
U.S. Patent No.: 6,961,088 B2	·)	
Issued: November 1, 2005)	January 30, 2006
Commissioner for Patents		entre service entre

CERTIFICATE OF CORRECTION

UNDER RULE 323

02/01/2006 SZEWDIE1 00000004 6961088

P.O. Box 1450

Alexandria, VA 22313-1450

01 FC:1811

100.00 DP

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

John A. Krause

Attorney for Patentees Registration No. 24,613

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

549290v1

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

6,961,088 B2

DATED

November 1, 2005

INVENTOR(S) :

TOSHIO KAMESHIMA ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 7

Line 25, "diagrams" should read --diagram--.

COLUMN 13

Line 13, "line." should read --lines.--; and Line 40, "common" should read --the common--.

COLUMN 14

Line 26, "wherein" should read --wherein,--; and Line 45, "is" should read --are--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone

(212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

549290v1

PATENT NO. US 6,961,088 B2

No. of add'l. copies @ 30¢ per page

■ _

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,961,088 B2

DATED

November 1, 2005

INVENTOR(S) :

TOSHIO KAMESHIMA ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 7

Line 25, "diagrams" should read --diagram--.

COLUMN 13

Line 13, "line." should read --lines.--; and Line 40, "common" should read --the common--.

COLUMN 14

Line 26, "wherein" should read --wherein,--; and Line 45, "is" should read --are--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,961,088 B2</u>

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

549290v1

